

Stevens Inspection
Univ of Cinn, OH

4/15/02

Model 405-28

Date of Mfg: 5/93

28' Type I Aluminum Extension

L Type II ! (Yellow caps, shoes, rope)

Base Section

Right Rail:

Run 4-5 Danger Label (F-1676)
(Electrocution Hazard)

5-6 Caution Label (F-1674)

6-7 Danger Label (F-2695)
(Failure to read)

13-14 28' label (F-2043-28)

Left Rail:

Run 4-5 Date Label (F-2872)
Month Mfg: J F M A M J J A S O N D
Year Mfg: 91 92 93 94 95 96 97

5-6 Label hand written

28' Alum Ext Ladder Type I
190 00

2032357

Rung 6-7 Use Label (F-1671)

13-14 28' label

Shoes: Trend intact
Dirty with some wear

Rungs: Wear from right RL on front edge of rungs
(Base -) Minimal scrapes at left RL contact area

Rung 7 - impact dent from (R) RL tip

7ly Section

Right Rail

Rung 2-3 "Caution - This ladder section is not
Designed for separate use"

12-13 Danger label (F-1675)
- Do not stand on or above

Top Green dot

Left Rail

Rung 2-3 Brown transfer on top flange
3-4 "Caution - This ladder section..."

5-6 Caution label (F-1717)
Electrical shock...

Rungs: 2#3 Scrapes with Brown transfer
4 Dented front aspect w/brown transfer

Ding Locks

Right - intact and functional

Left - broken casting about 1" below pivot
bolt